Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
L1	9000	((stress strain fatigue) near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:00
L2	77233	((stress strain fatigue) near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:00
L3	257	(((stress strain fatigue) near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)).clm.) and ((ligament slot) or (cut\$3 near2 (area portion part))). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:00
L4	308	(((stress strain fatigue) near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)).clm.) near3 test\$3.clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:00
L5	11	((((stress strain fatigue) near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)).clm.) near3 test\$3.clm.) and ((ligament slot) or (cut\$3 near2 (area portion part))).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:01
L6	98	((fatigue near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)) near5 (life test)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:01
L7	55	(((fatigue near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)) near5 (life test)).clm.) and "73"/\$. ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:01

L8	435	73/806-808.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:02
L9	13	73/806-808.ccls. and ((fatigue near4 (sens\$4 detect\$4 measur\$5 indicat\$4 identif\$5 determin\$5 monitor\$5 calculat\$5)) near5 (life damage test)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/07/27 15:02